



SHAPER DUO



Hexalobular Socket



Hexagon Socket




Square Socket



- Now available for Hexalobular(6-lobe) Socket
- Perfect fit for back spindle of Swiss machine
- Achieves good corner edge sharpness


- Less tool pressure than Rotary-Broaching
- Easy to adjust for correct dimension
- Economical double-ended insert bar (Except for Hexalobular)

Comparison Chart of Hexalobular Socket Machining

	Tool Pressure	Cycle Time	Tool Cost	High speed spindle	Program	
Shaper Duo 	◎	◎	◎	Not necessary	Simple	<ul style="list-style-type: none"> • No high speed spindle needed • A lot less cycle time
End milling	○	×	△	Necessary	Complicated	<ul style="list-style-type: none"> • Need high speed spindle • Time consuming process

- Small diameter endmill driven by high-speed spindle is popular way to create Hexalobular(6-lobe) socket. It has some flexibility but needs high speed spindle unit and it is a time consuming process.
- SHAPER DUO can make Hexalobular(6-lobe) socket faster and simpler.


Comparison Chart of HEX Socket Machining

	Tool Pressure	Cycle Time	Flexibility	Tool Cost	
Shaper Duo 	◎	△ * Can be off-set by over-wrapping operation	○	◎	<ul style="list-style-type: none"> • Less tool pressure-especially on small diameter parts • One size can cover several socket sizes
Broach Tool	△	○	×	△	<ul style="list-style-type: none"> • Need to have tools for each socket size

- Rotary-broach is an efficient way for Hexagon socket. But tool pressure is high and often it pushes part too hard.
- SHAPER DUO system enables less tool pressure and provides better tolerance with less cost.


Process Chart

① Center drilling




Make a center hole which is smaller than pilot hole drill.

② Drilling (Pilot hole)




Select a drill with same or smaller (0 ~ -0.1mm) dia. as AF and machine a bit deeper because burrs may cause chipping on shaper insert

③ Shaper tool




Machine socket rotating 60 degrees 6 times

④ Chamfering



Chamfer with the same pilot hole drill as ①

⑤ Deburring



Finish and deburr with the same drill as in process②
☆Reduce cutting conditions due to heavy interruption

SHAPER DUO Process Chart -Hexalobular-

Holder => K9

Socket Size	Tool	Pilot bore Dia. (mm)	Starting "X" position (mm)	Number of passes			Estimated cycle time *		
				Final "X" position (mm)	Roughing pass 0.025mm	Finishing pass 0.005mm	ISO10664 Standard depth of Hexalobular hole (mm)	Whole process ①-⑤	Process④ Shaper
T6	SSP050N25T06	1.15	1.14	1.75	13	1	1.82	51 sec	23.2 sec
T7	SSP050N31T07	1.38	1.35	2.06	15	1	2.44	59 sec	28.2 sec
T8	SSP050N36T08	1.62	1.59	2.40	17	1	3.05	67 sec	33.8 sec
T10	SSP050N41T10	1.92	1.89	2.80	19	1	3.56	75 sec	39.5 sec
T15	SSP050N43T15	2.30	2.29	3.35	22	1	3.81	84 sec	46.2 sec
T20	SSP050N46T20	2.71	2.69	3.95	26	1	4.07	94 sec	55.4 sec
T25	SSP050N50T25	3.13	3.09	4.50	29	1	4.45	105 sec	63.8 sec
T27	SSP050N55T27	3.52	3.51	5.07	32	1	4.70	115 sec	71.8 sec
T30	SSP050N55T30	3.91	3.89	5.60	35	1	4.95	125 sec	80.2 sec

* Using Carbide drill

* Shaper cutting conditions

Feed : 3000 mm/min

DOC : 0.025 mm (Roughing), 0.005 mm (Finishing)

SHAPER DUO Process Chart -Hexagonal-

Holder => K9

HEX Standard	Tool	Pilot bore Dia. (mm)	Starting "X" position (mm)	Number of passes			Estimated cycle time *		
				Final "X" position (mm)	Roughing pass 0.025mm	Finishing pass 0.005mm	ISO 2936 standard depth of Hex hole (mm)	Whole process ①-⑤	Process④ Shaper
HEX 1.5	SSP020N1130H	1.5	1.47	1.73	6	1	2	39 sec	14 sec
HEX 2.0	SSP020N1430H	2.0	1.95	2.31	8	1	2.5	44 sec	16 sec
HEX 2.5	SSP030N1940H	2.5	2.48	2.89	9	1	3	50 sec	20 sec
HEX 3.0	SSP030N1940H	3.0	2.95	3.46	11	1	3.5	55 sec	23 sec
HEX 4.0	SSP040N2450H	4.0	3.96	4.62	14	1	5	73 sec	33 sec
HEX 5.0	SSP050N3260H	5.0	4.96	5.77	17	1	6	90 sec	46 sec
HEX 6.0	SSP060N42120H	6.0	5.97	6.93	20	1	8	117 sec	63 sec
HEX 8.0	SSP080N62160H	8.0	7.98	9.24	26	1	10	155 sec	92 sec

* Pilot bore diameter is same or smaller(0-0.1mm) as AF.

* Shaper cutting conditions

Feed : 3000 mm/min

DOC : 0.025 mm (Roughing), 0.005 mm (Finishing)


* Using Carbide drill

Recommended Cutting Conditions

Feed : 3000 mm/min

DOC : Roughing ... 0.025 mm + Finishing ... 0.005 mm


Program Example → J6 · J7



Sleeves → K8 · K9

Shaper

Insert Bar -Hexalobular-




Single-sided

Item Number	Socket Size	Hexalobular Socket			D_s (mm)	L_2 (mm)	α (mm)	β (mm)	f (mm)	Pilot Bore Dia (mm)	Coated Carbide
		#	A (mm)	B (mm)							TM4
SSP050N25T06	T6	6	1.75	1.27	$\phi 5$	2.5	1.08	1.09	2.4	$\phi 1.15$	●
SSP050N31T07	T7	-	-	-	$\phi 5$	3.1	1.27	1.29	2.4	$\phi 1.38$	●
SSP050N36T08	T8	8	2.4	1.75	$\phi 5$	3.6	1.48	1.50	2.4	$\phi 1.62$	●
SSP050N41T10	T10	10	2.8	2.05	$\phi 5$	4.1	1.67	1.70	2.4	$\phi 1.92$	●
SSP050N43T15	T15	15	3.35	2.4	$\phi 5$	4.3	2.04	2.10	2.4	$\phi 2.30$	●
SSP050N46T20	T20	20	3.95	2.85	$\phi 5$	4.6	2.41	2.50	2.4	$\phi 2.71$	●
SSP050N50T25	T25	25	4.5	3.25	$\phi 5$	5.0	2.78	2.90	2.4	$\phi 3.13$	●
SSP050N55T27	T27	-	-	-	$\phi 5$	5.5	3.15	3.30	2.4	$\phi 3.52$	●
SSP050N55T30	T30	30	5.6	4.05	$\phi 5$	5.5	3.52	3.70	2.4	$\phi 3.91$	●

※Caution: Due to the tolerance, it might not fit into the holder which is made by other company.

Sleeves →K8 · K9

Insert Bar -Hexagon-




Double-sided

Item Number	Base AF (mm)	HEX Standard size range (mm)	AF range (mm)	D_s (mm)	L_1 (mm)	L_2 (mm)	h_1 (mm)	α (mm)	β (mm)	f (mm)	Coated Carbide
											TM4
SSP020N1130H	HEX 1.5	HEX 1.5 - 2.0	1.4 - 2.0	$\phi 2$	50	3.0	1.8	1.1	0.8	0.40	●
SSP020N1430H	HEX 2.0	HEX 2.0 - 2.5	1.9 - 2.6	$\phi 2$	50	3.0	1.8	1.4	1.1	0.55	●
SSP030N1940H	HEX 3.0	HEX 2.5 - 3.5	2.4 - 3.6	$\phi 3$	50	4.0	2.8	1.9	1.6	0.8	●
SSP040N2450H	HEX 4.0	HEX 3.5 - 4.5	3.4 - 4.6	$\phi 4$	60	5.0	3.8	2.4	2.6	1.3	●
SSP050N3260H	HEX 5.0	HEX 4.5 - 6.0	4.4 - 6.2	$\phi 5$	70	6.0	4.8	3.2	3.4	1.70	●
SSP060N42120H	HEX 6.0	HEX 6.0 - 8.0	5.9 - 8.2	$\phi 6$	80	12.0	5.6	4.2	4.0	2.00	●
SSP080N62160H	HEX 8.0	HEX 8.0 - 12.0	7.9 - 12.2	$\phi 8$	80	16.0	7.6	6.2	4.7	2.35	●

※Caution: Due to the tolerance, it might not fit into the holder which is made by other company.

Sleeves →K8 · K9

Insert Bar -Square-



Double-sided

Item Number	Base AF (mm)	AF range (mm)	D_s (mm)	L_1 (mm)	L_2 (mm)	h_1 (mm)	α (mm)	β (mm)	f (mm)	Coated Carbide
										TM4
SSP020N1740S	2.0	1.9 - 2.3	$\phi 2.0$	50	4.0	1.8	1.70	1.60	0.70	●
SSP025N1940S	2.5	2.2 - 2.6	$\phi 2.5$	50	4.0	2.3	1.95	1.80	0.65	●
SSP030N2260S	3.0	2.5 - 3.0	$\phi 3.0$	50	6.0	2.8	2.20	2.05	0.65	●
SSP035N2760S	3.5	2.9 - 3.7	$\phi 3.5$	60	6.0	3.3	2.70	2.25	0.60	●
SSP040N3380S	4.0	3.6 - 4.6	$\phi 4.0$	60	8.0	3.8	3.35	3.05	1.15	●
SSP050N39100S	5.0	4.5 - 5.4	$\phi 5.0$	70	10.0	4.8	3.90	3.95	1.55	●
SSP060N47120S	6.0	5.3 - 6.6	$\phi 6.0$	80	12.0	5.6	4.75	4.50	1.70	●
SSP080N58160S	8.0	6.5 - 8.1	$\phi 8.0$	80	16.0	7.6	5.80	5.50	1.70	●


※Caution: Due to the tolerance, it might not fit into the holder which is made by other company.

Sleeves →K8 · K9

● : Stock


SHAPER DUO Set-up Instructions - Hexagonal

Outside machine





- Set the insert bar in the sleeve and check the parallelism of the flat portion of the sleeve and the insert bar.
- Minimize the overhang of the insert.

Inside machine




- Set the sleeve into the tool post and make sure the sleeve is set parallel.
- Minimize sleeve overhang.





- Increase the number of machining passes with smaller depth of cut if the insert chips with large depth of cut. (0.025mm×5pass is recommended)
No chamfering process is required for measuring purpose.
- Measure the length of both [a] and [b] with comparator or magnifier.
- Adjust centerline height by rotating the sleeve until you get the same length for [a] and [b]. (The difference should be less than 0.02mm)
*If the straight is not seen with increased passes, please reset the insert and the sleeve.
Please make sure both the insert and the sleeve are set up correctly.

4 Machine Hexagonal shape

- Run full HEX machining program.



For Hexalobular machining Basically same as Hexagonal socket



Hexagon Socket Programming Code Examples from Machine Builders in Metric

Hex socket size : Hex 3.0mm, AF(Final "X" position) 3.46mm, Depth 3.5mm
Pilot drill diameter : 3.0mm **Starting "X" position :** 2.95mm (see chart on J3)
Insert : SSP030N1940N TM4
Parameters : Feed 3000mm/min, DOC(Roughing) 0.025mm, (Finishing) 0.005mm

■ Programming tips

● Make a program considering final " X "position.

- #1 Final "X" position : 3.46mm (AF)
- #2 Finishing position of roughing : $3.46 - 0.01$ (Finishing) = 3.45mm
- #3 Calculate total DOC for roughing : $3.45 - 3.0$ (Pilot hole) = 0.45mm
- #4 Determine number of cuts : $0.45 \div 0.05$ (DOC for Dia.) = $9.0 + 2$ (round down to whole number and add "2" for program adjustment)
 → Roughing sequence runs 11 times
- #5 Set starting point : $3.45 - (0.05 \times (11 - 1)) = 2.95\text{mm}$: must subtract by "1" for program adjustment

■ CITIZEN

Main Program Sequence

```
M25
M78 S0 .....I
Shaper T****
G50 U1.6 .....II
G0 X2.95 Z-2.0 T** .....III
M98 P2100 L11 .....IV
M98 P2200 .....V
```

```
M78 S60 .....I
G0 X2.95 Z-2.0
M98 P2100 L11
M98 P2200 } <a>
```

Repeat <a> program sequence 4 more times to complete the cuts at S120, S180, S240, S300 (represents 120°, 180°, 240°, 300°).

```
M20
G0 Z-2.0
G50 U-1.6
G0 U0 W0 T0
M1
```

■ STAR

Main Program Sequence

```
M25
Shaper T****
G50 U1.6 .....II
M8
G0 X2.95 Z-2.0 C0 T** .....I, III
M98 P2100 L11 .....IV
M98 P2200 .....V
```

```
G0 C60.0 .....I
G0 X2.95 Z-2.0
M98 P2100 L11
M98 P2200 } <a>
```

Repeat <a> program sequence 4 more times to complete the cuts at C120.0, C180.0, C240.0, C300.0 (represents 120°, 180°, 240°, 300°).

```
G0 Z-2.0
G50 U-1.6
G0 T0
G28 W0
M1
```

■ TSUGAMI

Main Program Sequence

```
M105
M150
G28 H0 .....I
M182
Shaper T****
G50 U1.6 .....II
G0 X2.95 Z2.0 T** .....III
M98 P2100 L11 .....IV
M98 P2200 .....V
M183
```

```
G0 C60 .....I
M182
G0 X2.95 Z2.0
M98 P2100 L11
M98 P2200 } <a>
```

Repeat <a> program sequence 4 more times to complete the cuts at C120, C180, C240, C300 (represents 120°, 180°, 240°, 300°).

```
M151
G0 Z2.0
G50 U-1.6
G0 U0 W0 T0
M1
```

Sub-Program Sequence #1 for Roughing

```
N2100
G4 U0.02 .....A
G98 G1 Z3.5 F3000 .....B
G4 U0.02
U-0.2 W-0.018 .....C
G4 U0.02
G0 Z-2.0
G4 U0.02
U0.25 .....D
M99
```

Sub-Program Sequence #1 for Roughing

```
O2100
G4 U0.02 .....A
G98 G1 Z3.5 F3000 .....B
G4 U0.02
U-0.2 W-0.018 .....C
G4 U0.02
G0 Z-2.0
G4 U0.02
U0.25 .....D
M99
```

Sub-Program Sequence #1 for Roughing

```
O2100
G4 U0.02 .....A
G98 G1 Z-3.5 F3000 .....B
G4 U0.02
U-0.2 W0.018 .....C
G4 U0.02
G0 Z2.0
G4 U0.02
U0.25 .....D
M99
```

Sub-Program Sequence #2 for Finishing

```
N2200
G98 G1 X3.46 Z-2.0 F1000 .....E
G4 U0.02
Z3.5 F3000
G4 U0.02
U-0.2 W-0.018
G4 U0.02
G0 Z-2.0
M99
```

Sub-Program Sequence #2 for Finishing

```
O2200
G98 G1 X3.46 Z-2.0 F1000 .....E
G4 U0.02
Z3.5 F3000
G4 U0.02
U-0.2 W-0.018
G4 U0.02
G0 Z-2.0
M99
```

Sub-Program Sequence #2 for Finishing

```
O2200
G98 G1 X3.46 Z2.0 F1000 .....E
G4 U0.02
Z-3.5 F3000
G4 U0.02
U-0.2 W0.018
G4 U0.02
G0 Z2.0
M99
```

- I. Index the sub-spindle 6 times in 60 degree increments.
- II. Specify the coordinate system shift command (in X axis direction) for the tool. [2 x f, where f is tool dimension located in catalog].
 - A positive direction shift is recommended for easier programming.
- III. Execute the positioning of the tool.
 - X position should be smaller than pilot drill diameter.
 - Z position should be offset 2.0 mm from material to achieve program feed rate.
- IV. Go to the Sub-Program #1.
 - Sequence runs 11 times. First cutting point X2.95 and final cutting point X3.45, with 0.05 DOC (for diameter) each time.

- A. Specify dwell time. This allows the program and machine to stay synchronized.
- B. Cut into part 3.5mm. F3000 is recommended feed to be used for most materials; including Titanium Alloy and Stainless Steel.
- C. This code backs off the tool with an angle greater than 6 degrees (10 degrees used in example). See page J3.
- D. Return to the X position + 0.05mm (the DOC for diameter).
- V. Go to the Sub-Program #2, for finishing sequence.
- E. Finishing operation with 0.005mm DOC (X 3.46) is recommended for better surface finish.

Hexalobular Socket Programming Code Examples from Machine Builders in Metric

Hexalobular socket size : Hexalobular T15 (depth : 3.81mm)

Pilot drill diameter : 2.3mm

Insert : SSP050N43T15 TM4

Parameters : Feed 3000mm/min, DOC(Roughing) 0.025mm, (Finishing) 0.005mm

■ Programming tips

● **Make a program considering final “ X ” position.**

- #1 Final “ X ” position : 3.35mm(A)
- #2 Finishing position of roughing : $3.35 - 0.01$ (Finishing) = 3.34mm
- #3 Calculate total DOC for roughing : $3.34 - 2.3$ (Pilot hole) = 1.04mm
- #4 Determine number of cuts : $1.04 \div 0.05$ (DOC for Dia) = 20.8 + 2 (round down to whole number and add “2” for program adjustment)
→ Roughing sequence runs 22 times
- #5 Set starting point : $3.34 - (0.05 \times (22 - 1)) = 2.29$ mm : must subtract by “1” for program adjustment

■ CITIZEN

Main Program Sequence

```
M25
M78 S0 .....I
Shaper T****
G50 U4.8 .....II
G0 X2.29 Z-2.0 T** .....III
M98 P2100 L22 .....IV
M98 P2200 .....V
```

```
M78 S60 .....I
G0 X2.29 Z-2.0
M98 P2100 L22 } <a>
M98 P2200 }
```

Repeat <a> program sequence 4 more times to complete the cuts at S120, S180, S240, S300 (represents 120°, 180°, 240°, 300°).

```
M20
G0 Z-2.0
G50 U-4.8
G0 U0 W0 T0
M1
```

■ STAR

Main Program Sequence

```
M25
Shaper T****
G50 U4.8 .....II
M8
G0 X2.29 Z-2.0 C0 T** .....I, III
M98 P2100 L22 .....IV
M98 P2200 .....V
```

```
G0 C60.0 .....I
G0 X2.29 Z-2.0
M98 P2100 L22 } <a>
M98 P2200 }
```

Repeat <a> program sequence 4 more times to complete the cuts at C120.0, C180.0, C240.0, C300.0 (represents 120°, 180°, 240°, 300°).

```
G0 Z-2.0
G50 U-4.8
G0 T0
G28 W0
M1
```

■ TSUGAMI

Main Program Sequence

```
M105
M150
G28 H0 .....I
M182
Shaper T****
G50 U4.8 .....II
G0 X2.29 Z2.0 T** .....III
M98 P2100 L22 .....IV
M98 P2200 .....V
M183
```

```
G0 C60 .....I
M182
G0 X2.29 Z2.0
M98 P2100 L22 } <a>
M98 P2200
M183
```

Repeat <a> program sequence 4 more times to complete the cuts at C120, C180, C240, C300 (represents 120°, 180°, 240°, 300°).

```
M151
G0 Z2.0
G50 U-4.8
G0 U0 W0 T0
M1
```

Sub-Program Sequence #1 for Roughing

```
N2100
G4 U0.02 .....A
G98 G1 Z3.81 F3000 .....B
G4 U0.02
U-0.2 W-0.018 .....C
G4 U0.02
G0 Z-2.0
G4 U0.02
U0.25 .....D
M99
```

Sub-Program Sequence #1 for Roughing

```
O2100
G4 U0.02 .....A
G98 G1 Z3.81 F3000 .....B
G4 U0.02
U-0.2 W-0.018 .....C
G4 U0.02
G0 Z-2.0
G4 U0.02
U0.25 .....D
M99
```

Sub-Program Sequence #1 for Roughing

```
O2100
G4 U0.02 .....A
G98 G1 Z-3.81 F3000 .....B
G4 U0.02
U-0.2 W0.018 .....C
G4 U0.02
G0 Z2.0
G4 U0.02
U0.25 .....D
M99
```

Sub-Program Sequence #2 for Finishing

```
N2200
G98 G1 X3.35 Z-2.0 F1000 .....E
G4 U0.02
Z3.81 F3000
G4 U0.02
U-0.2 W-0.018
G4 U0.02
G0 Z-2.0
M99
```

Sub-Program Sequence #2 for Finishing

```
O2200
G98 G1 X3.35 Z-2.0 F1000 .....E
G4 U0.02
Z3.81 F3000
G4 U0.02
U-0.2 W-0.018
G4 U0.02
G0 Z-2.0
M99
```

Sub-Program Sequence #2 for Finishing

```
O2200
G98 G1 X3.35 Z2.0 F1000 .....E
G4 U0.02
Z-3.81 F3000
G4 U0.02
U-0.2 W0.018
G4 U0.02
G0 Z2.0
M99
```

- I. Index the sub-spindle 6 times in 60 degree increments.
- II. Specify the coordinate system shift command (in X axis direction) for the tool. [2 x f, where f is tool dimension located in catalog].
 - A positive direction shift is recommended for easier programming.
- III. Execute the positioning of the tool.
 - X position should be smaller than pilot drill diameter.
 - Z position should be offset 2.0 mm from material to achieve program feed rate.
- IV. Go to the Sub-Program #1.
 - Sequence runs 22 times. First cutting point X2.29 and final cutting point X3.34, with 0.05 DOC (for diameter) each time.

- A. Specify dwell time. This allows the program and machine to stay synchronized.
- B. Cut into part 3.81mm. F3000 is recommended feed to be used for most materials; including Titanium Alloy and Stainless Steel.
- C. This code backs off the tool with an angle greater than 6 degrees (10 degrees used in example). See page J3.
- D. Return to the X position + 0.05mm (the DOC for diameter).
- V. Go to the Sub-Program #2, for finishing sequence.
- E. Finishing operation with 0.005mm DOC (X 3.35) is recommended for better surface finish.